

**ITB 17-0404, Poured In Place Rubber Surface Repair and Maintenance for Lake County Parks****Bid Due Date: October 5, 2016****Contracting Officer: Sandra Rogers, CPPB**

This is an indefinite quantity contract with no guarantee services will be required. The County does not guarantee a minimum or maximum dollar amount to be expended on the contract resulting from this ITB. Prices and payments shall be full compensation for all services as specified in Section 2, Scope of Services, including all materials, equipment, fuel, labor, tools, and supervision to complete each project.

Miller Recreation Equipment & Design, Bradenton, FL		
Description	Sq. Ft. Price ( Amenities)	Sq. Ft. Price (Without Amenities)
Cost to remove and replace existing broken or damaged rubber surface material which is ½” thick	\$10.65	\$11.65
Cost to remove and replace existing broken or damage rubber surface material which is 1” thick	\$12.50	\$13.50
Cost to remove and replace existing broken or damaged rubber surface material which is 1 ½” thick	\$13.30	\$14.30
Cost to remove and replace existing broken or damaged rubber surface material which is 2” thick	\$14.10	\$15.10
Cost per square foot for surface sealer application (Aliphatic Polyurethane Binder)	\$2.25	\$2.25

By submitting estimated complete SF below the bidder certifies that a site visit has been made where work is to be performed and confirms complete compliance with provision 1.4 of this Invitation To Bid.

Park	Estimated complete SF of rubber surface at each park
Lake Idamere Park	18440
Twin lakes Park	1650
Paisley Community Park	812
McTureous Memorial Park	4189

Play Space Services, Inc. (Melbourne, FL) has been found to be non-responsive.